

**ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Division of Spill Prevention and Response**  
**Prevention and Emergency Response Program**

**SITUATION REPORT**

**INCIDENT NAME:** FV Wild Coho

**SITREP #:** 1

**SPILL NUMBER:** 04119903401

**LEDGER CODE:** 1951360

**TIME/DATE OF SPILL:** The spill occurred when the boat sank during the night of February 2-3, 2004. ADEC was notified by the Yakutat ADF&G office at 8:45 AM, February 3, 2004.

**TIME/DATE OF SITUATION REPORT :** 12:00 PM, February 3, 2004

**TIME/DATE OF THE NEXT REPORT:** 12:00 PM, February 4, 2004

**TYPE/AMOUNT OF PRODUCT SPILLED:** The owner estimates 200 gallons of diesel was aboard the vessel when it sank. The tank vent pipes have not been plugged so the spill may be up to 200 gallons.

**LOCATION:** Yakutat small boat harbor, Yakutat.

**CAUSE OF SPILL:** Vessel sank at the dock during a period of heavy snowfall.

**POTENTIAL RESPONSIBLE PARTY (PRP):** Mr. Bill Lucey, Yakutat, Alaska.

**RESPONSE ACTION:** The owner set sorbent boom over the sunken vessel. SART has authorized the use of 20' containment boom and other supplies from the ADEC response container in Yakutat. A diver made an assessment of the situation this morning but determined that the vessel, suspended from the dock by a single line, presented too great a risk to allow plugging the fuel tank vents. An ADEC responder was dispatched from Juneau and is on scene to monitor and assist in the response. ADEC will provide on-scene assistance and monitoring and will also coordinate response with USCG.

**SOURCE CONTROL:** Sorbent boom has been set in place and ADEC containment boom is being deployed. A diver will plug the vents if the vessel is stabilized enough to allow safe diving conditions.

**RESOURCES AFFECTED:** Yakutat small boat harbor. ADEC has received no reports of oiled wildlife.

**FUTURE PLANS AND RECOMMENDATIONS:** Owner will complete booming the vessel with containment boom and collect oil using sorbent materials. Owner is pursuing available options to plug the vents and raise the vessel. ADEC will coordinate response actions with the owner and the USCG.

**WEATHER:** 34°F with periods of snow possibly mixed with rain, east winds 10-15 mph changing to southeast at 10-15 mph tonight. Rain and snow predicted tonight and tomorrow.

**UNIFIED COMMAND AND PERSONNEL:**

Incident Commander:	Mr. Bill Lucey (RP)
F.O.S.C.:	CDR John Sifling (USCG)
S.O.S.C.:	Bob Mattson (ADEC)
Field S.O.S.C.:	Scot Tiernan (ADEC)

**FOR ADDITIONAL INFORMATION CONTACT:** Bob Mattson, ADEC at 465-5349. Other spill information is available for viewing at <http://www.state.ak.us/dec/spar/perp/index.htm>

**AGENCY/STAKEHOLDER NOTIFICATION LIST**

<b>Agency</b>	<b>Name</b>	<b>Sent Via</b>	<b>Additional Info</b>	<b>Telephone</b>	<b>Fax</b>
ADFG	Mark Fink	Email	mark_fink@fishgame.state.ak.us	267-2338	267-2464
ADNR	Doug Sanvik	Email	<a href="mailto:doug_sanvik@dnr.state.ak.us">doug_sanvik@dnr.state.ak.us</a>	465-3400	465-3513
USCG (MSO Juneau)	CDR John Sifling	Email	<a href="mailto:jsifling@cgalaska.uscg.mil">jsifling@cgalaska.uscg.mil</a>	463-2453	463-2445
USCG (MSO Juneau)	Lt. Tyrone Jones	Email	<a href="mailto:tljones@cgalaska.uscg.mil">tljones@cgalaska.uscg.mil</a>	463-2470	463-2445
EPA	Matt Carr	Email	Sent via Spill Report Group	271-3616	271-3424
NMFS	Jon Kurland	Email	<a href="mailto:Jon.kurland@noaa.gov">Jon.kurland@noaa.gov</a>	586-7638	586-7358
<b>Other</b>	<b>Name</b>	<b>Sent via</b>	<b>Additional Info</b>	<b>Telephone</b>	<b>Fax</b>
Senate/ Dist. C	Georgianna Lincoln	Fax	Session: Interim:	465-3732 888-461-3732	465-2652 465-2652
House/ Dist. 5	Albert Kookesh	Fax	Session: Interim:	465-3473 788-3501	465-2827 788-3176
City & Borough of Yakutat Mayor	Victoria Demmert	Fax	Email: C/O bmanager@ptialaska.net	784-3323	784-3281
SEAPRO	Dave Owings	Fax	<a href="mailto:dave@seapro.org">dave@seapro.org</a>	225-7002	247-1117